

The items highlighted (yellow) have been completed, the other items will be sorted by Mark and I through this week

- Medlar court - 2 no. gates need repairing, neither gate self closes – Installation of 2 monhinge complete closer set and damper kits £1,425.00
- Alton Close - Gate not fully closing – Installation of x1 prosafe repair kit £555.00
- St Marks - To fit 1 no. self closing gate spring £48.75
- Churchward -To fit spring assisted gate spring £51.00
- Mannington - Gate is closing too slowly. Installation of Easy gate repair kit £331.50

Additional items identified through Marks inspections:

- X2 Pendulum seat sets (chains and covers included, these are for Inglesham Road and Medlar Court zip lines) £270.69 ****Will only put the one up at Medlar, will keep Inglesham back until we decide what going on with the frame****
- X2 Curve flat seats (Inglesham Road Swings) £148.79
- X4 Oilite Bush – Wickstead type (Mannington junior swings) £72.00
- X1 blank HDPE panel (replace damaged board at Alton close) £223.77

Total cost - £5,266.00

We had the play installers out today to take a look at the frame for the zip line at Inglesham Rd, as per Marks reports he has noticed issues with the wooden framework (Inglesham Road end) these posts are very loose and have loads of play in them.

The guys have reported back that it would wise to remove the zip line seat as the frame is rotten in multiple locations, with this in mind we will take down tomorrow morning.

Prices to replace:

- Steel frame £15,975.70
- Timber £21,825.49

Allocated Play budget - £27,500

Current play area running balance - £9,125.76

1) Mannington

Play Bark levels low

We have noted some of the wet pout surfacing has eroded and needs to be addressed.

2) Harcourt Rd

Gate – in progress

Carpet (exposed concrete)

Replacement bushes

Seesaw

3) St Marks

Gates – In progress

Play bark (exposed concrete)

Rotten wood

Screws and bolts sticking out

4) Churchward

Bolts sticking out of swing barrier.

5) Pembroke Garden

Twisted / unsecure chains

Missing mats

6) Alanbrooke

Surfacing

7) Inglesham

Exposed concrete

Weeds

Split seat

Bushes worn

Unsecure safety chain

Zip wire – Significant

8) Minety

Uneven surface / gaps

Weeds

Exposed metal bracket

9) Medlar

Branch Removal

Exposed concrete

Tree trunks / holes

Exposed metal and bushes worn

Worn chains

Damaged seat

Missing panels

Sharp edges

10) Chapel St

Loose posts

Exposed concrete

Weeds