













Barnum Court				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x				
Furniture	x				
Bins					
Signs	x			Bolts inside	
Surface			x	Exposed concrete, uneven, weeds, holes, gaps and splits	
Train Climber	x			Damage to fall boards, damaged step, movement in tunnel and nail sticking out of step	
Spring Aeroplane			x	Exposed concrete, damaged wood and broken handle	
Rocking Moose			x	Remove metal bracket	
Additional Comments					
Signature				Contract Manager Signature	



Churchward Park				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x			One gate has a broken spring the other gate not self closing	
Furniture	x				
Bins	x				
Signs	x			Bolts on the inside	
Surface	x			Mats receding, weeds and holes	
Multiplay Junior	x			Damaged steps and caps plus 2x caps missing	
Spring Aeroplane	x				
Spring See Saw	x			Split frame and broken handle	
Swings (Kids)	x			Needed to re tighten swing bolt	
Swing Barrier	x				
Additional Comments					
Signature				Contract Manager Signature	


Mannigton Park				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x				
Furniture	x				
Bins	x			Dog bin by car park bridge needs replacing	
Signs	x			bolts inside	
Surface			x	Exposed concrete, exposed roots, exposed membrane, weeds, uneven and wooden beam sticking out of pathway	
Rocking Elephant	x				
Spring Basket					
Freestanding slide	x			Missing bolt cap	
Mixed Seat Swing Set	x				
Play Panel	x				
Musical Panel	x				
Basket Swing	x			Has been removed	
Swing Panels			x	Exposed concrete and one panel missing	
Rope Climber			x	Exposed concrete and roots	
Swings Junior	x			both swings removed due to bushes and bolts	
Multiplay Junior	x				
Stepping Stones					
MUGA			x	Damage to one panel long piece sticking out	
Additional Comments					
one log crumbling another split in half length ways and damage to pathway around outside of muga, lots of branches fallen down on pathway between changing rooms and play park.					
Signature			Contract Manager Signature		



Alanbrooke Close				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x			Damage by gate, gate now passing through fence entrapment issue	
Gates	x			One gate shutting too slowly	
Furniture	x				
Bins	x				
Signs	x			Bolts inside	
Surface	x			Uneven, splits, weeds and holes	
Stepping Stones	x			Worn edges	
Multiplay Junior	x				
Swing (kids)	x				
Swings (Junior)	x			Change bushes	
Aeroplane Springer	x				
Spring Dog	x			Damage to wood	
Additional Comments					
holes in surface					
Signature				Contract Manager Signature	
					



Harcourt Road				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates			x	Missing stopper and closing too slowly	
Furniture	x				
Bins	x				
Signs	x			Bolts on the inside	
Surface	x			Lump by fence from old bracket, gaps, splits and weeds	
Spring Lion			x	Has been removed	
Spring Tractor	x			Loose spring have twisted to tighten up	
Supanove Spinner	x				
Balance Beam	x				
Play Panel	x				
Toadstools	x			damage to edges	
See Saw (Large)	x			Worn footrests and gaps around flooring below	
Swings Kids	x				
Swings Junior	x				
Multiplay Junior	x				
Additional Comments					
Signature				Contract Manager Signature	

St Marks Park				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x			black circled fence has a broken piece	
Gates			x	one gate has a missing stopper and not fully closing and sandpit gate not self closing gate spring pulled out and bent	
Furniture	x				
Bins	x				
Signs	x			Bolt on the inside	
Surface			x	Exposed concrete, weeds and wood sticking out of path by gate in toddler area	
Spring Elephant	x				
Spring Bike	x				
Basket Swing			x	Exposed stone under swing	
Swings (Junior)	x			Damage to seats	
Rope Climber	x				
Basket Roundabout	x				
Embankment Slide			x	Corners of slide brackets sticking out	
Steps	x			Uneven steps	
Rope Bridge	x			Missing straps, bolts sticking out and 2 nuts missing either end of rope	
Stepping Stones	x				
Kickabout Wall			x	Exposed concrete, missing panel, screws and bolts sticking out, raised wooden edge and loose rotten posts	
Muga	x			Damage to one panel and missing bolts	
Statue	x				
Additional Comments					
Sandpit area has exposed membrane, wooden beams, exposed concrete around gate posts at sand pit and fences around the fountain and sand pit have points sticking out on each connection and the new fence at the whip planting area had fallen					
Signature				Contract Manager Signature	



Medlar Close				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x			damage to one gate and is catching on the surface	
Furniture			x	Branch hanging from tree	
Bins	x				
Signs	x			Bolts inside	
Surface			x	Exposed concrete, multiple holes dug, weeds and 2x tree trunks removed from fenced area	
Wobble Board			x	Exposed concrete and missing handle	
Multiplay Junior		x		Damaged/missing boards and bolts sticking out	
Swing			x	Exposed concrete and damaged seat exposing metal and bushes need replacing	
Climbing Frame			x	Exposed concrete	
Basket Swing			x	Exposed concrete and brick, small burn damage to seat	
Cable Runway			x	Exposed concrete, loose steps, one step broken and two step missing	
Tai Chi Wheels	x			missing handles	
Rower			x	Exposed concrete and rust in places	
Space Walker	x			Rust on some welds and lump by post	
Activity Trail		x		Worn rope exposing wire and damaged stepping stones	
Spring car	x				
MUGA			x	Missing panels & bolts, Damage to multiple panels exposing sharp edges and hole in surface	
Additional Comments					
basket swing removed, metal bracket uncovered as well as small stumps by the gym equipment, hole found by pinehurst road entrance and litter pick was needed and carried out during inspection					
Signature				Contract Manager Signature	



Pinetrees				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x			One damaged panel and loose posts	
Gates	x			one gate dropped	
Furniture	x			Bench has been removed	
Bins	x				
Signs	x				
Surface	x				
Hut	x			Bent roof	
Multi Sound Pannel	x				
Space Dish	x			This was in use but looked to be working	
Swing	x				
Spiral spinner	x			red slider bit is stuck	
Slide	x			Cap missing and one loose foot peg one footrest has moved and now points inwards slightly	
Additional Comments					
Gate closest to entrance broken with screws and nails sticking out, plastic cup full of cigarette butts on fence and cans on the floor					
Signature				Contract Manager Signature	



Wilcox Close				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x			two panels missing, bolts missing, loose panel and damaged posts	
Gates	x				
Furniture					
Bins					
Signs	x			Bolts inside	
Surface	x			hole by swings mats receding, gaps, uneven and holes	
Slide	x				
Swing (kids)	x				
Spring Motorbike					
Additional Comments					
Signature				Contract Manager Signature	


Chapel Street				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence		x		Rotten posts and kickboards, missing kickboards and exposed nails	
Gates			x	Loose posts, missing stopper and one has snapped spring	
Furniture			x	Exposed concrete at bench	
Bins	x				
Signs	x			Bolts inside	
Surface			x	Exposed concrete, membrane and weeds	
Multiplay Senior	x			One bolt missing on climber wall	
Supanova spinner	x				
Basket Swing	x				
MUGA	x				
Flower	x				
Spring Chair	x				
Goal Posts	x			Loose posts	
Fitness Equipment	x				
Additional Comments					
Pathway from car park to play area damaged					
Signature				Contract Manager Signature	
					

Trowbridge Close				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates					
Furniture	x			Rope hanging from tree	
Bins					
Signs					
Surface	x			Animal holes	
Spring Boards x3	x			Split on one base cover	
Act Trail	x			Missing and loose and rotten stepping stones	
Rope Climber	x				
Spinner	x				
Balance beam	x			Has been removed	
Additional Comments					
Pile of green waste					
Signature		Contract Manager Signature			

Alton close				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x			Not fully closing	
Furniture	x			Low canopy from tree	
Bins	x			Broken base slab	
Signs	x			Bolts on the inside	
Surface			x	Uneven, gaps and missing flooring	
Pendulum Swing	x			Has been removed	
Multiplay Junior		x		One fall board is damaged, rust on net bracket, loose leaf step, damage to tunnel board, mutiple bolt covers missing, one bracket cover missing and soft/split surface at bottom of slide	
Swing (kids)	x				
Swings (Junior)	x			split on seats	
Low Rotator (Spinner)	x				
Dish Roundabout	x				
See Saw (Small)	x			Mechanism broken	
See Saw (Large)	x				
Additional Comments					
Signature				Contract Manager Signature	

Minety Road				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x			one gate has been pulled out with post	
Furniture			x	Gaps and uneven surface at bench	
Bins	x				
Signs	x			bolts inside	
Surface			x	Weeds, gaps, uneven and small fire damage	
Multiplay Toddler	x			Worn rope exposing wire, damage to 2 fall boards and loose handrail (needs tightening)	
Basket Swing	x				
Cable Runway	x			Loose steps, seat perishing	
Spring Bike		x		Hole in the seat	
MUGA	x			Damaged and loose fence panel	
Additional Comments					
Signature			Contract Manager Signature		

Ingelsham Road				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence			x	Wall leaning & split, tennis fence in poor state and bent bracket on metal fence	
Gates	x			Not fully closing	
Furniture	x				
Bins	x				
Signs	x			Bolts inside	
Surface			x	Exposed concrete & holes on mound getting bigger, gaps, uneven, weeds and animal hole behind mound	
Net Climber		x		Worn rope exposing wire and one step has damage to the edge	
Multiplay Junior	x			bolt missing from bridge step and hole in surface by tunnel	
Swing (kids)	x				
Swings (Junior)	x			one swing waiting on repair	
Basket Swing (Wooden)		x		Split frame, broken chain cover, one safety chain screw hanging out and seat has been removed	
Climbing Frame	x				
Basket Swing	x			Has been removed	
Supanova Spinner	x				
Space Net		x		Sunkern feet and one mat was moved	
See Saw	x				
Cable Runway	x				
Monkey Bars	x			Split frame	
Trampoline	x			Raised edges	
Talk Tubes	x				
Rope Climber (large)	x			3x Broken links on blue net	
MUGA	x				
Leg Press	x				
Ski Stepper	x			some rust	
Spinning Bike	x				
Hand Bike	x			Squeeking	
Sit up bench	x				
In space sign	x				
Power Push	x				
Additional Comments					
Bolt missing where fence meets the gate and bolt sticking out slightly on multiplay fall panel					
Signature				Contract Manager Signature	

Pembroke Gardens				Date	23/02/2026
Equipment	Risk Level			Inspector Name	Mark Richards
	Low	Medium	High	Comments	
Fence	x				
Gates	x				
Furniture	x				
Bins	x				
Signs	x				
Surface	x				
Basket swing	x				
Trampoline	x				
Cable Runway	x			Loose steps and missing bolts	
Roundabout	x				
Bee play board	x			Purple flower not spinning freely like the green one, sun spinner also not spinning freely	
Multiplay	x			some damaged washers and washer sticking out at one part	
2 Spring trains	x				
Spinning seesaw	x			Damage to seat possibly by a dog	
Multiboard hut	x				
Additional Comments					
all hand turning parts are either really stiff or catching in certain areas					
Signature				Contract Manager Signature	